

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

EE655 VS # 3318  
ESE BRIGHTON BEACH AVE/6TH ST  
1/2-1 BROOKLYN, NY

NY Spills S104651899  
N/A

0.958 mi.  
5060 ft.

Site 2 of 2 in cluster EE

Relative:  
Higher

SPILLS:

Actual:  
9 ft.

Name: VS # 3318  
Address: BRIGHTON BEACH AVE/6TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0000686 / 2002-01-03  
Facility ID: 0000686  
Facility Type: ER  
DER Facility ID: 179457  
Site ID: 216740  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2000-04-17  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2000-04-17  
CID: 233  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2000-04-17  
Spill Record Last Update: 2002-01-03  
Spiller Name: CALLER  
Spiller Company: CON ED  
Spiller Address: 4 IRVING PL  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL Con Ed e2mis #130924 Notes: 4-17-00 1910hrs 10gal dielectric fluid in VS3318. Transformer is below minimum. Structure has earthen sump as per records. Historical records show 10ppm PCB. Sample taken. Cleanup pending feeder 7b44 removed from service. 4-18-00 0155hrs LSN 00-03767 15ppm PCB 4-18-00 0300hrs 250gal oil drained from transformer. 4-18-00 1700hrs Flush Dept completed cleanup. Took a grab sample from sump. Sump was cemented. Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. Transformer replaced. No leaking equipment."  
Remarks: "con ed # 130924 spill confined in vault clean up pending lab results no sewers or water ways involved"

All Materials:

Site ID: 216740  
Operable Unit ID: 822403  
Operable Unit: 01  
Material ID: 288926  
Material Code: 0541A  
Material Name: dielectric fluid

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported